

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/2/27	MAKE	CAT	MODEL	910Z
SERIAL	40Y05179	STAMP	40Y05179		
HR METER	8800	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB	ROPS CNP / CNP / NONE	TIRE SIZE	16.9-24	10PR (SNOW)

ENGINE : MODEL 3204DI S/N 45V37639	
Oil leakage	FAIR · ☒ Attn *1
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · ☒ NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · ☒ DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · ☒ Attn 穴、破れあり HOLES, CUT
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · ☒ H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · ☒ Attn *2
Bell crank	FAIR · Attn
Bucket	FAIR · Attn *3
Articulate	FAIR · ☒ Attn *4

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
下周り油漏れあり(吸着マットあり)	
BOTTOM: OIL LEAKING (W/ABSORPTION MAT)	
タコメーター TACHOMETER: 47431km	
STEERING TYPE WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	YES · ☒ OTHER スノーブレード SNOW BLADE
BLADE	YES · ☒ NO Piping for Tilt ☒ YES · NO
COMMENT	
スピードメーター不良 SPEEDOMETER: MALFUNCTION	
下周り油漏れあり(吸着マットあり)	
BOTTOM: OIL LEAKING (W/ABSORPTION MAT)	
機体外装リペイントあり REPAINTED	
*1 E/G周り油漏れあり(吸着マットあり)	
*1 AROUND ENGINE: OIL LEAKING (W/ABSORPTION MAT)	
*2 左右シリンダーにじみあり(吸着マットあり)	
*2 CYLINDERS: OIL OOZING (W/ABSORPTION MAT)	
*3 ブレード右シリンダーにじみあり(吸着マットあり)	
*3 RIGHT CYLINDER: OIL OOZING (W/ABSORPTION MAT)	
*4 左シリンダーにじみあり(吸着マットあり)	
*4 LEFT CYLINDER: OIL OOZING (W/ABSORPTION MAT)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。