

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/3/12	MAKE	UNI CARRIERS	MODEL	705-2
SERIAL	57E00367			STAMP	B13-00367
HR METER	1445	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			TIRE SIZE	27 × 8.50-15 4PR

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
OPERATION PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<u>PS</u> · DD	
Transmission	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · <u>Attn</u> *1	
FOOT BRAKE	<u>FAIR</u> · <u>Attn</u>	効かない MALFUNCTION
PARKING BRAKE	<u>FAIR</u> · <u>Attn</u>	効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
FRONT & CYLINDERS		
Arm	<u>FAIR</u> · Attn	
Bell crank	<u>FAIR</u> · Attn	
Bucket	<u>FAIR</u> · <u>Attn</u>	穴あり、亀裂あり HOLE, MUCH CRACKED
Articulate	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	<u>FAIR</u> · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / <u>LEVER STEERING</u>	
RIDE CONTROL	YES · <u>NO</u>
ATTACHMENTS	
STD BKT	<u>YES</u> · OTHER
BLADE	YES · <u>NO</u> Piping for Tilt YES · <u>NO</u>
COMMENT	
ワーニングランプ点灯あり WARNING LAMP: ON	
右走行レバー: ニュートラルポジションにならない	
RIGHT TRAVEL LEVER: UNABLE TO STAY AT THE NEUTRAL POSITION	
*1 右走行モーター弱い RIGHT TRAVEL MOTOR: WEAK POWER	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。