

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/3/24	MAKE	TADANO	MODEL	TR-100M-1
SERIAL No.	PLATE : FC0939		STAMP : TR100-0939		
HR METER	7849	HR	Odometer	160984	km
TIRE SIZE	11R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	MLモニター映り悪い MONITOR: BLURRED
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION		
Transmission	<input checked="" type="radio"/> FAIR · Attn	
No. OF GEARS	3 GEARS	
4WD	<input checked="" type="radio"/> 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	シート破れあり CUT, HOLES
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
COMMENT		

BOOM			
No. of Section	6 SECTIONS		
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn		
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	油漏れあり OIL LEAKING	
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn		
JIB	YES · <input checked="" type="radio"/> NO		
JIB TYPE	STD · PWR		
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO *1		
HOOK	10t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR	<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR		
COMMENT			
後方ステアリングシリンダーに繋がるホース油漏れあり			
HOSE ATTACHES WITH REAR STEERING CYLINDER: OIL LEAKING			
OUTRIGGERS			
OUTRIGGERS	<input checked="" type="radio"/> X · H		
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
エア一漏れあり AIR LEAKING			
主ウインチモーター油漏れあり MAIN WINCH MOTOR: OIL LEAKING			
E/Gとターボの繋ぎ目排気漏れあり			
CONNECTING PART BETWEEN ENGINE & TURBO: EXHAUST LEAKING			
*1 主巻ワイヤーサビ大 MAIN WIRE: MUCH RUSTY			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。