

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/3/21	MAKE	KOBELCO	MODEL	7055
SERIAL No.	PLATE : GB00516	STAMP	GB00516 ("GB": HARD TO READ)		
HR METER	8150 / 2701 HR	SHOE	760FLAT	YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	未確認 NOT CHECKED
Swing	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	*1
Travel	<input checked="" type="radio"/> FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 1, 6m × 1, 3m × 1	
BOOM TOTAL	30m	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR	<input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	*2
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · <input checked="" type="radio"/> H only	· C only · None
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1	
COMMENT		
左右シューたるみあり TRACK LINKS: WORN		
アクセル吹けない ACCELERATOR: UNABLE TO REV UP		
WEIGHT	2	
HOOK	55t, 32t, BALL	
LIFTER	YES · <input checked="" type="radio"/> NO	
COMMENT		
レバー中立注意 LEVER: HARD TO STAY AT THE NEUTRAL POSITION		
CAB後ろ側低圧ホース油漏れあり		
LOW PRESSURE HOSE OF REAR SIDE OF CAB: OIL LEAKING		
コンピュータ解除で操作可 NEED TO CUT THE COMPUTER TO OPERATE		
*1 ロック不良、キャタ張り出しできないため旋回不可		
*1 SWING LOCK: MALFUNCTION, UNABLE TO SWING (CRAWLER EXTENSION: MALFUNCTION)		
*2 破れ、取付不良 TORN, MOUNTING PART: MALFUNCTION		
@NARITA YARD		
BOOM: TOP, BOTTOM, WEIGHT × 1, 55t HOOK		
@SAKURA YARD		
BOOM: 9m × 1, 6m × 1, 3m × 1, WEIGHT × 1, HOOK: 32t, BALL		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。