## INSPECTION SHEET 検品書 CRAWLER CRANE クローラクレーン

INSPECTIO	N DATE	2025/3/28	MAKE	E	SUMITOMO	MODEL	SC900-3		
SERIAL No.	PLATE: SC090-1534		STAMP		SC090-1534				
HR METER	69	89 HR	SHOE	1	810FLAT	YEAR		YR	
ENGINE :	MODEL	S/N	I 313	3504	INTERIOR S	See Photos.	写真参照		
Oil leakage	FAIR · Attn				INTERIOR COND.	CLEAN • (	FAIR · DIRTY		
Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE					Operator's Seat FAIR Attn				
Sound FAIR · Attn					Glasses FAIR Attn				
Oil	FAIR · Attn				AirCon A/C	H/C	• H only • C only •	None	
Exhaust Color	FAIR · Attn				UNDERCARRIA	GE: See	e Photos. 写真参照		
OPERATIO	N PUM	<u> </u>			RUST (5: NONE, 4: A	LITTLE, 3: MID	DLE, 2: MUCH, 1: CORRODED)	3	
Sound FAIR · Attn				COMMENT					
Oil leakage	FAIR · Attn								
Power	FAIR · Attn								
COOLING SYSTEM					WEIGHT	3			
Radiator FAIR · Attn *1				ноок	90t, 50t, 35t, BALL				
Oil Cooler	FAIR · Attn				LIFTER	YES · NO			
OPERATING SYSTEM					COMMENT				
Computer	OK)· NG	未確認 NOT Ch	HECKED		*1 外側サビ大	OUTSIDE O	F RADIATOR: MUCH RU	ISTY	
Swing	FAIR · Attn								
Travel FAIR · Attn				@NARITA YARD					
воом					BOOM: TOP, BOTTOM, 9m×1				
MAIN BOOM TOP, BOTTOM, 9m × 2, 6m × 2, 3m × 1, 2m × 1, 1m × 1				HOOK: BALL					
воом т	OTAL	48m							
					@SAKURA YARI	)			
TOP SHEAVE YES · NO				BOOM: 9m×1, 6m×2, 3m×1, 2m×1, 1m×1					
JIB					HOOK: 90t, 50t,	OOK: 90t, 50t, 35t			
TOWE	ER								
					RUST of BODY (5: NON	IE, 4: A LITTLE, 3:	MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。