

**INSPECTION SHEET 検品書
EXCAVATOR バックホー**

INSPECTION DATE	2025/3/4	MAKE	KOMATSU	MODEL	PC40MR-3
SERIAL	23763		STAMP	KMTPC203EFE023763	
HR METER	2276	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	350R	

ENGINE : MODEL 4D88E S/N

Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES · <input checked="" type="radio"/> NO

MAIN PUMP

Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn

OPERATING SYSTEM

Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn

INTERIOR See Photos. 写真参照

Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None

BOOM / ARM / BKT

Boom	<input checked="" type="radio"/> FAIR · Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn
Arm	<input checked="" type="radio"/> FAIR · Attn ガタあり LOOSE
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn
BKT	<input checked="" type="radio"/> FAIR · Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
BKT	STD <input checked="" type="radio"/> SLOPE NARROW / SKELETON / OTHER ()	
Lever	LONG · <input checked="" type="radio"/> WRIST	
Multi	MULTI · 2 · <input checked="" type="radio"/> NO	
ARM-CRANE	YES · <input checked="" type="radio"/> NO	
BLADE	<input checked="" type="radio"/> YES · NO	
OFFSET	YES · <input checked="" type="radio"/> NO	
OFFSET Cylinder	FAIR · Attn	
Piping	<input checked="" type="radio"/> YES · NO Breaker only <input checked="" type="radio"/> Multi	

COMMENT

スイング部ガタあり SWING PART: LOOSE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。