INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/3/7	MAKE	KATO	MODEL	KR-10H-L Ⅱ
SERIAL No.	PLATE : 3910590		STAMP : KR102-0590		
HR METER	19841 HR		Odometer	88382 km	
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR · (Attn)	E/G上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	FAIR · (Attn)	A LITTLE · (MIDDLE) · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	FAIR · (Attn)	油漏れあり OIL LEAKING
No. OF GEARS	3 GEARS	
No, of DRIVE WHEELS	4 WD	
INTERIOR See Photos. 写真参照		
Operator's Seat	(FAIR) · Attn	
Inside Cover	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	(FAIR) · Attn	
DERRICKING CYL.	(FAIR) · Attn	
EXTENSION CYL.	(FAIR) · Attn	
JIB	(YES) · NO	
JIB TYPE	(STD) · PWR	
MAIN & SUB WIRE	(YES) · NO	
HOOK	10t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1
COMMENT		
OUTRIGGERS		
OUTRIGGERS	X · (H)	
OUTRIGGERS COND.	(FAIR) · Attn	
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。