

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|----------------|------|--------------------|-------|-----------|
| INSPECTION DATE | 2025/3/7 | MAKE | TADANO | MODEL | GR-250N-1 |
| SERIAL No. | PLATE : FB5021 | | STAMP : TR256-1735 | | |
| HR METER | 12093 | HR | Odometer | 73822 | km |
| TIRE SIZE | 385/95R25 | | YEAR | YR | |

| ENGINE : MODEL | S/N |
|----------------------------------|--|
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn <input checked="" type="radio"/> A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil | <input checked="" type="radio"/> FAIR · Attn |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn |
| OPERATION PUMP | |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Power | <input checked="" type="radio"/> FAIR · Attn |
| COOLING SYSTEM | |
| Radiator | <input checked="" type="radio"/> FAIR · Attn |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn |
| OPERATING SYSTEM | |
| Computer | <input checked="" type="radio"/> OK · NG *1 |
| Swing | <input checked="" type="radio"/> FAIR · Attn |
| Travel | <input checked="" type="radio"/> FAIR · Attn |
| TRANSMISSION | |
| Transmission | <input checked="" type="radio"/> FAIR · Attn |
| No. OF GEARS | 4 GEARS |
| No. of DRIVE WHEELS | 4 WD |
| INTERIOR See Photos. 写真参照 | |
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn 破れあり CUTS |
| Inside Cover | <input checked="" type="radio"/> FAIR · Attn |
| Glasses | <input checked="" type="radio"/> FAIR · Attn |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |
| COMMENT | |
| | |

| BOOM | |
|--|--|
| No. of Section | 4 SECTIONS |
| CRACK/ENFORCEMENT | <input checked="" type="radio"/> FAIR · Attn |
| DERRICKING CYL. | <input checked="" type="radio"/> FAIR · Attn |
| EXTENSION CYL. | <input checked="" type="radio"/> FAIR · Attn 油漏れあり OIL LEAKING |
| JIB | <input checked="" type="radio"/> YES · NO |
| JIB TYPE | STD · <input checked="" type="radio"/> PWR |
| MAIN & SUB WIRE | <input checked="" type="radio"/> YES · NO |
| HOOK | 25t, BALL |
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 1 |
| COMMENT | |
| 左Rタイヤサイド外側、左右Fタイヤサイド内側亀裂あり | |
| OUTSIDE REAR LEFT TIRE SIDEWALL & INSIDE FRONT TIRE SIDEWALLS: CRACKED | |
| OUTRIGGERS | |
| OUTRIGGERS | X · <input checked="" type="radio"/> H |
| OUTRIGGERS COND. | <input checked="" type="radio"/> FAIR · Attn |
| COMMENT | |
| ロータリーホース油漏れあり SWING HOSE: OIL LEAKING | |
| *1 CPUエラー表示、FUELエラー表示あり CPU & FUEL ERRORS DISPLAY | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。