

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2025/3/11	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE			
MAKE	LIEBHERR		MODEL	LTM1100N-3		
SERIAL	063322		STAMP	W094747004EL05073		
HR METER	13955 / CHASSIS: 4016	HR	Odometer	38306 km	YEAR	YR
CHASSIS	MODEL	No.		TIRE	445/95R25	

ENGINE(CRANE) : MODEL		S/N		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	<input checked="" type="radio"/> FAIR · Attn			
Oil	<input checked="" type="radio"/> FAIR · Attn			
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn			
ENGINE(CHASSIS) : MODEL		S/N		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	<input checked="" type="radio"/> FAIR · Attn			
Oil	<input checked="" type="radio"/> FAIR · Attn			
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn			
OPERATION PUMP				
Sound	<input checked="" type="radio"/> FAIR · Attn			
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			
Power	<input checked="" type="radio"/> FAIR · Attn			
COOLING SYSTEM				
Radiator	<input checked="" type="radio"/> FAIR · Attn			
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn			
OPERATING SYSTEM				
Computer	<input checked="" type="radio"/> OK · NG			
Swing	<input checked="" type="radio"/> FAIR · Attn			
Travel	<input checked="" type="radio"/> FAIR · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	<input checked="" type="radio"/> AT · MT	無段変速 CVT	No. OF GEARS	- GEARS
Transmission	<input checked="" type="radio"/> FAIR · Attn			
No. of DRIVE WHEELS	8	WD		
Travel	<input checked="" type="radio"/> FAIR · Attn			
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn			
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn			
INTERIOR See Photos. 写真参照				
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn			
Inside Cover	<input checked="" type="radio"/> FAIR · Attn			
Glasses	<input checked="" type="radio"/> FAIR · Attn			
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · NONE			

CRANE	
WEIGHT	8
HOOK	90t, 59t, 26t, BALL
BOOM	
MAIN BOOM	-
BOOM TOTAL	
No. of Section	6 SECTIONS
TOP SHEAVE	<input checked="" type="radio"/> YES · NO
JIB	STD · <input checked="" type="radio"/> PWR
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
左ステアリングシリンダー油漏れあり FRONT LEFT STEERING CYLINDER: OIL LEAKING	
OUTRIGGERS	
OUTRIGGERS	<input checked="" type="radio"/> FAIR · Attn H-TYPE
FRONT JACK	YES · <input checked="" type="radio"/> NO
COMMENT	
100rメインフック欠 100t HOOK: MISSING	
@NARITA YARD	
WEIGHT × 3	
HOOK: 90t, BALL	
@SAKURA YARD	
WEIGHT × 5, JIB × 2	
HOOK: 59t, 26t	
MANY PARTS	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。