

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/6/3	MAKE	KOMATSU	MODEL	PW200-1
SERIAL	10146	STAMP	10146		
HR METER	7758	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	10.00R20	YEAR	
				YR	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO

MAIN PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	油汚れあり OIL STAINS
Power	FAIR・Attn	

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Swing	FAIR・Attn	ガタあり SWING: LOOSE
Travel	FAIR・Attn	

INTERIOR	See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり A LITTLE DAMAGED
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT		
Boom	FAIR・Attn	
Boom Cylinder	FAIR・Attn	左油漏れあり LEFT CYLINDER: OIL LEAKING
Arm	FAIR・Attn	ガタあり LOOSE
Arm Cylinder	FAIR・Attn	
BKT	FAIR・Attn	
BKT Cylinder	FAIR・Attn	油漏れ、傷あり OIL LEAKING, SCRATCHED

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT			
左右Fダンパーシリンダー油漏れあり			
FRONT DAMPER CYLINDERS: OIL LEAKING			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG	• (WRIST)	
Multi	MULTI	• 2 • (NO)	
ARM-CRANE	YES	• (NO)	
BLADE	(YES)	• NO	*1
OFFSET	YES	• (NO)	
OFFSET Cylinder	FAIR	• Attn	
Piping	(YES)	• NO	Breaker only • (Multi) *2
OUTRIGGERS COND.	FAIR	• Attn	

COMMENT	
クーラー配管破損あり PIPE OF COOLER: BROKEN	
エア溜まるのが遅い AIR: SLOW TO STORE	
*1 カケ、穴、パッチあり PARTLY CHIPPED OFF, HUGE HOLES, PATCHED	
*2 左側ホース欠 LEFT HOSE: PARTLY MISSING	
</	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。