INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/2	MAKE	TADANO	MODEL	TR-500M-3
SERIAL No.	PLATE : 581530		STAMP : TR551-0083		
HR METER	2275 HR		Odometer	51717 km	
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・(Attn)	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR・(Attn)	A LITTLE・MIDDLE・(SEVERE)
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	(FAIR)・Attn	
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Computer	(OK)・NG	
Swing	(FAIR)・Attn	
Travel	(FAIR)・Attn	
TRANSMISSION		
Transmission	(FAIR)・Attn	
No. OF GEARS	4 GEARS	
4WD	(4WD)・6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・FAIR・(DIRTY)	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C)・H/C・H only・C only・None	
COMMENT		
CAB前面ヘコミ大 FRONT PART OF CAB: MUCH DENT		

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	(FAIR)・Attn	
DERRICKING CYL.	(FAIR)・Attn	
EXTENSION CYL.	(FAIR)・Attn	
JIB	(YES)・NO	
JIB TYPE	STD・(PWR)	
MAIN & SUB WIRE	(YES)・NO	
HOOK	50t, 25t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1
TIRE WEAR	(FAIR)・WORN・UNEVEN WEAR	
COMMENT		
Fバンパーヘコミ大 FRONT BUMPER: MUCH DENT		
OUTRIGGERS		
OUTRIGGERS	(X)・H	
OUTRIGGERS COND.	(FAIR)・Attn	
Oil leakage (JACK CYL.)	FRONT L・R	REAR L・R
Oil leakage (SLIDE CYL.)	FRONT L・R	REAR L・R
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。