INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/7	MAKE	KOBELCO	MODEL	RK250-6
SERIAL No.	PLATE : EZ08-09082		STAMP : EZ08-9082		
HR METER	24421 HR		Odometer	44727 km	
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Computer	OK・NG	
Swing	FAIR・Attn	
Travel	FAIR・Attn	
TRANSMISSION		
Transmission	FAIR・Attn	*1
No. OF GEARS	3 GEARS	
4WD	4WD・6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
COMMENT		
ドア開閉不良 DOOR: MALFUNCTION TO OPEN or CLOSE		

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	FAIR・Attn	
DERRICKING CYL.	FAIR・Attn	
EXTENSION CYL.	FAIR・Attn	
JIB	YES・NO	
JIB TYPE	STD・PWR	
MAIN & SUB WIRE	YES・NO	
HOOK	25t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR・WORN・UNEVEN WEAR	
COMMENT		
OUTRIGGERS		
OUTRIGGERS	X・H	
OUTRIGGERS COND.	FAIR・Attn	
Oil leakage (JACK CYL.)	FRONT L・R	REAR L・R
Oil leakage (SLIDE CYL.)	FRONT L・R	REAR L・R
COMMENT		
*1 トルコンケース下部にじみあり		
*1 BOTTOM OF TORQUE CONVERTER CASE: OIL OOZING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。