

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/3/6	MAKE	MAEDA	MODEL	MC-275C
SERIAL No.	PLATE : 395126	STAMP		395126	
HR METER	UNKNOWN HR	SHOE	180R	YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input type="radio"/> OK · <input type="radio"/> NG	
Swing	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1	
BOOM		
MAIN BOOM		
BOOM TOTAL		
TOP SHEAVE	<input type="radio"/> YES · <input checked="" type="radio"/> NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	<input type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input checked="" type="radio"/> None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
カニクレーン SPIDER CRANE		
5段ブーム 5-SECTION BOOM		
WEIGHT	-	
HOOK	2.5t	
LIFTER	<input type="radio"/> YES · <input checked="" type="radio"/> NO	
COMMENT		
排気パイプ腐食、断裂あり EXHAUST PIPE: CORRODED, BROKEN		
アクセルレバー: ローアイドル方向に戻る		
ACCELERATOR LEVER: RETURNING TO LOW IDLING SIDE		
右Fアウトリガーシリンダーにじみあり		
FRONT RIGHT OUTRIGGER CYLINDER: OIL OOZING		
左Rアウトリガーシリンダー油漏れあり		
REAR LEFT OUTRIGGER CYLINDER: OIL LEAKING		
過巻防止効かない OVERWINDING PREVENTION: MALFUNCTION		
付属品: リモコン REMOTE CONTROL AS SPARE		
*1 右側走行レバー反応悪い		
*1 RIGHT TRACK: HARD TO OPERATE BY THE TRAVEL LEVER		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。