

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2025/3/6	MAKE	KOBELCO	MODEL	SK75SR-3
SERIAL	YT07-26247		STAMP	YT07-26247	
HR METER	4701	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	*1
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	破れあり TORN
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	へコミあり DENT
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	穴あり MUCH CRACKED
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG · (WRIST)
Multi	(MULTI) · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · (NO)
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · (Multi)
COMMENT	
オルタネーターベルト鳴きあり ALTERNATOR BELT: NOISES	
E/Gフードカバーラッチ不良 ENGINE HOOD LATCH: MALFUNCTION	
*1 前進時のウサギ走行時右足遅い	
*1 RIGHT TRACK: SLOW MOVING WITH THE LOW GEAR DURING TRAVELING FORWARD	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。