

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/31	MAKE	HITACHI	MODEL	ZX450LC
SERIAL	HCM16J00L00010788		STAMP	HCM16J00L00010788	
HR METER	8346	HR	YEAR	2003	YR
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	SHOE	600G		

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	<u>YES</u> · NO	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>	
Operator's Seat	<u>FAIR</u> · Attn	破れあり TORN
Glasses	<u>FAIR</u> · Attn	
AirCon	<u>A/C</u> · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · Attn	3段ブーム 3-SECTION BOOM
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	*1

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u> 5 *2
COMMENT	
ブーム背面ホースひび割れあり	
SOME HOSES AROUND LOWER PART OF BOOM: CRACKED	
コード切れあり(アタッチメント用?) CORD (FOR ATTACHMENT?): CUT	
スタンダードバケット外れあり(付属品扱い)	
STANDARD BUCKET: NOT ATTACHED (AS SPARE)	
付属品: スタンダードバケット、アーム、2ピースブーム、中間ブーム1本、台座	
STANDARD BUCKET, ARM, 2-PIECE BOOM,	
INSERT BOOM, & FIXING STAND AS SPARE	
*1 シリンダー配管外れあり CYLINDER HOSE: NOT ATTACHED	
*2 配管ホースひび割れあり SOME HOSES: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。