

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	2025/4/2	MAKE	KOMATSU	MODEL	LW100M-1E
SERIAL No.	PLATE :	10384		STAMP :	L004-10384
HR METER	5950	HR	Odometer	32696	km
TIRE SIZE	11R22.5		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE <input type="radio"/>
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG <input type="radio"/>	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	3 GEARS	
4WD	4WD <input checked="" type="radio"/> 6WD <input type="radio"/>	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN <input type="radio"/> FAIR <input checked="" type="radio"/> DIRTY <input type="radio"/>	
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None <input type="radio"/>	
<b>COMMENT</b>		

<b>BOOM</b>			
No. of Section	6 SECTIONS		
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn		
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn		
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn		
JIB	YES <input type="radio"/> NO <input checked="" type="radio"/>		
JIB TYPE	STD <input type="radio"/> PWR <input type="radio"/>		
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO <input type="radio"/>		
HOOK	4.9t, BALL		
<b>UNDERCARRIAGE : See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN <input type="radio"/> UNEVEN WEAR <input type="radio"/>		
<b>COMMENT</b>			
<b>OUTRIGGERS</b>			
OUTRIGGERS	X <input type="radio"/> H <input checked="" type="radio"/>		
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L <input type="radio"/> R <input type="radio"/>	REAR L <input type="radio"/> R <input type="radio"/>
Oil leakage (SLIDE CYL.)	FRONT	L <input type="radio"/> R <input type="radio"/>	REAR L <input type="radio"/> R <input type="radio"/>
<b>COMMENT</b>			
*1 上部油漏れあり UPPER PART OF ENGINE: OIL LEAKING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。