

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/3/25	MAKE	KATO	MODEL	KR-25H-V8
SERIAL No.	PLATE : 6710308		STAMP : KRC011-0308		
HR METER	19201	HR	Odometer	113129	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	4 GEAR	
4WD	(4WD) · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	*1
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM									
No. of Section		4		SECTIONS					
CRACK/ENFORCEMENT		FAIR		▪ Attn					
DERRICKING CYL.		FAIR		▪ Attn					
EXTENSION CYL.		FAIR		▪ Attn					
JIB		YES		▪ NO					
JIB TYPE		STD		▪ PWR					
MAIN & SUB WIRE		YES		▪ NO					
HOOK		25t, BALL							
UNDERCARRIAGE : See Photos. 写真参照									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								1	
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR							
COMMENT									
OUTRIGGERS									
OUTRIGGERS		X		▪ H					
OUTRIGGERS COND.		FAIR		▪ Attn					
Oil leakage (JACK CYL.)		FRONT		L ▪ R		REAR		L ▪ R	
Oil leakage (SLIDE CYL.)		FRONT		L ▪ R		REAR		L ▪ R	
COMMENT									
*1 パワーウィンドウ: CAB内のS/Wだと上がらない									
*1 POWER WINDOWS: UNABLE TO CLOSE BY THE SWITCH IN CAB									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。