INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2025/4/8	CATEGORY	(ON-ROAD DUMP) ・ OFF-ROAD DUMP
MAKE	KOMATSU	MODEL	HD405-7
SERIAL	7843	STAMP	KMTHD030V29007843
HR METER	22972 HR	ODOMETER	99079 km
TIRE SIZE	18.00R33	YEAR	2013 YR

ENGINE : MODEL S/N		
Oil leakage	(FAIR) ・ Attn	
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	
US EPA	YES ・ (NO)	
OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	
COOLING SYSTEM		
Radiator	(FAIR) ・ Attn	
Oil Cooler	(FAIR) ・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(AT) ・ MT	No. OF GEARS 6 GEARS
Transmission	(FAIR) ・ Attn	
4WD	(4WD) ・ 2WD	
Travel	(FAIR) ・ Attn	
Articulate	FAIR ・ Attn	
FOOT BRAKE	(FAIR) ・ Attn	
PARKING BRAKE	FAIR ・ (Attn)	効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR) ・ Attn	
Glasses	(FAIR) ・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	

MAIN FRAME		
MAIN FLAME	(FAIR) ・ Attn	
VESSEL		
MAKE		
VESSEL	FAIR ・ (Attn)	*1
REAR GATE TYPE	NORMAL ・ L-GATE (FLAT)	
REAR GATE	FAIR ・ Attn	
UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	(FAIR) ・ WORN ・ UNEVEN WEAR	

COMMENT

ROPS-CAB

E03表示あり "E03" ERROR DISPLAY

ファンベルト鳴きあり FAN BELT: NOISES

燃料タンク下ホース周り燃料漏れ小

AROUND SOME PIPE UNDER FUEL TANK: FUEL LEAKING

*1 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。