

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |                                        |      |      |       |                   |
|-----------------|----------------------------------------|------|------|-------|-------------------|
| INSPECTION DATE | 2025/3/10                              | MAKE | CAT  | MODEL | 313DCR            |
| SERIAL          | CAT0313DPLCE00303                      |      |      | STAMP | CAT0313DPLCE00303 |
| HR METER        | 6240 / 6249                            | HR   | YEAR | YR    |                   |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 500G PADS         |

|                                  |                                    |                               |
|----------------------------------|------------------------------------|-------------------------------|
| <b>ENGINE : MODEL</b>            |                                    | <b>S/N</b>                    |
| Oil leakage                      | FAIR • Attn                        |                               |
| Blow-By                          | FAIR • Attn                        | A LITTLE • MIDDLE • SEVERE    |
| Sound                            | FAIR • Attn                        |                               |
| Oil                              | FAIR • Attn                        |                               |
| Exhaust Color                    | FAIR • Attn                        |                               |
| US EPA                           | YES • NO                           |                               |
| <b>MAIN PUMP</b>                 |                                    |                               |
| Sound                            | FAIR • Attn                        |                               |
| Oil leakage                      | FAIR • Attn                        |                               |
| Power                            | FAIR • Attn                        |                               |
| <b>COOLING SYSTEM</b>            |                                    |                               |
| Radiator                         | FAIR • Attn                        |                               |
| Oil Cooler                       | FAIR • Attn                        |                               |
| <b>OPERATING SYSTEM</b>          |                                    |                               |
| Swing                            | FAIR • Attn                        |                               |
| Travel                           | FAIR • Attn                        |                               |
| <b>INTERIOR See Photos. 写真参照</b> |                                    |                               |
| INTERIOR COND.                   | CLEAN • FAIR • DIRTY               |                               |
| Operator's Seat                  | FAIR • Attn                        |                               |
| Glasses                          | FAIR • Attn                        |                               |
| AirCon                           | A/C • H/C • H only • C only • None |                               |
| <b>BOOM / ARM / BKT</b>          |                                    |                               |
| Boom                             | FAIR • Attn                        |                               |
| Boom Cylinder                    | FAIR • Attn                        | 左右油漏れ小 CYLINDERS: OIL LEAKING |
| Arm                              | FAIR • Attn                        |                               |
| Arm Cylinder                     | FAIR • Attn                        |                               |
| BKT                              | FAIR • Attn                        |                               |
| BKT Cylinder                     | FAIR • Attn                        |                               |

|                                                                      |                                             |
|----------------------------------------------------------------------|---------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                             |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3                                           |
| <b>COMMENT</b>                                                       |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
| BKT                                                                  | STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG • WRIST                                |
| Multi                                                                | MULTI • 2 • NO                              |
| ARM-CRANE                                                            | YES • NO                                    |
| BLADE                                                                | YES • NO                                    |
| OFFSET                                                               | YES • NO                                    |
| OFFSET Cylinder                                                      | FAIR • Attn                                 |
| Piping                                                               | YES • NO Breaker only • Multi               |
| <b>COMMENT</b>                                                       |                                             |
| モニター画面フリーズする時あり                                                      |                                             |
| (検品時一度だけクレーンモードのバケット巻き込みを行った時に発生、                                    |                                             |
| キーOFFで画面切れずメインでOFF)                                                  |                                             |
| MONITOR: FROZEN ONCE AT THE INSPECTION TIME                          |                                             |
| (HAPPENED WHEN DRAWING THE BUCKET IN CRANE MODE,                     |                                             |
| MONITOR: UNABLE TO BE OFF BY KEY, ABLE TO BE OFF BY MAIN SWITCH)     |                                             |
| A/C異音あり A/C: NOISES                                                  |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                             |
| 3                                                                    |                                             |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。