INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/4	MAKE	KOMATSU	MODEL	PC128UU-8
SERIAL	28285			STAMP	KMTPC189C01028285
HR METER	6855 HR			YEAR	YR
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	底板油漏れ小 BOTTOM: OIL LEAKING
Blow-By	(FAIR)・Attn	A LITTLE・MIDDLE・ SEVERE
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	(FAIR)・Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Swing	(FAIR)・Attn	
Travel	(FAIR)・Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・Attn	
Boom Cylinder	(FAIR)・Attn	
Arm	(FAIR)・Attn	
Arm Cylinder	(FAIR)・Attn	
BKT	(FAIR)・Attn	
BKT Cylinder	(FAIR)・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	(MULTI) ・ 2 ・ NO	
ARM-CRANE	(YES) ・ NO	
BLADE	(YES) ・ NO	
OFFSET	(YES) ・ NO	
OFFSET Cylinder	(FAIR) ・ Attn	
Piping	YES ・(NO)	Breaker only ・ Multi
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。