

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2025/4/3	MAKE	HITACHI	MODEL	ZX135US-5B
SERIAL	HCMDAEA0L00092619		STAMP	HCMDAEA0L00092619	
HR METER	6690	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

**ENGINE : MODEL** 4JJ1 **S/N** 178845

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

**MAIN PUMP**

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

**OPERATING SYSTEM**

Swing	FAIR	Attn	
Travel	FAIR	Attn	

**INTERIOR** See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

**BOOM / ARM / BKT**

Boom	FAIR	Attn	ガタあり LOOSE
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

**RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

**COMMENT**

.....  
 .....  
 .....  
 .....

**BKT** (STD) / SLOPE / NARROW / SKELETON / OTHER ( )

**Lever** LONG · (WRIST)

**Multi** (MULTI) · 2 · NO

**ARM-CRANE** YES · NO

**BLADE** YES · NO

**OFFSET** YES · (NO)

**OFFSET Cylinder** FAIR · Attn

**Piping** YES · (NO) Breaker only · Multi

**COMMENT**

Iリンクガタあり I-LINKS: LOOSE

.....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....

**RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。