

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2025/4/1	MAKE	CAT	MODEL	D3K2LGP
SERIAL	CAT00D3KTKL207555			STAMP	CAT00D3KTKL207555
HR METER	2106	HR	SHOE	630LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

<b>ENGINE : MODEL</b> C4.4 S/N	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	<input checked="" type="radio"/> YES · NO
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE	<input checked="" type="radio"/> PS · DD DIFF. STEERING YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	<input checked="" type="radio"/> CLEAN FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>BLADE &amp; CYLINDERS</b>	
BLADE	<input checked="" type="radio"/> FAIR · Attn
CYLD.(R)	<input checked="" type="radio"/> FAIR · Attn
CYLD.(L)	<input checked="" type="radio"/> FAIR · Attn
TILT CYLD	<input checked="" type="radio"/> FAIR · Attn
ANGLE CYLD	<input checked="" type="radio"/> FAIR · Attn

<b>UNDERCARRIAGE See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
Ripper	MULTI · S/S Shanks PCS
Ripper CYLD.	<input checked="" type="radio"/> FAIR · Attn
EQUALIZER BAR	<input checked="" type="radio"/> FAIR · Attn
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。