

INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE		2025/3/11	CATEGORY	ON-ROAD DUMP · OFF-ROAD DUMP	
MAKE	ISUZU		MODEL	PB-FRR35G3	
SERIAL	7000200		STAMP	FRR35G3-7000200	
HR METER	UNKNOWN	HR	ODOMETER	315974	km
TIRE SIZE	225/80R17.5 (SNOW, STUDLESS)		YEAR	YR	

ENGINE : MODEL		6HL1	S/N	
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
OPERATION PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	AT · MT	クラッチレスMT CMT	No. OF GEARS	6 GEARS
Transmission	FAIR · Attn			
4WD	4WD · 2WD			
Travel	FAIR · Attn			
Articulate	FAIR · Attn			
FOOT BRAKE	FAIR · Attn			
PARKING BRAKE	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn	破れあり CUT		
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			

MAIN FRAME					
MAIN FLAME		FAIR	・ Attn	*1	
VESSEL					
MAKE					
VESSEL		FAIR	・ Attn	リペイントあり REPAINTED	
REAR GATE TYPE		NORMAL ・ L-GATE (FLAT)			*2
REAR GATE		FAIR	・ Attn	リペイントあり REPAINTED	
UNDERCARRIAGE:		See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR		FAIR	WORN ・ UNEVEN WEAR		
COMMENT					
最高出力 MAXIMUM OUTPUT: 140kW (190PS)/2900rpm					
*1 サビ、リペイントあり RUSTY, REPAINTED					
*2 観音開き DOUBLE DOORS					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。