

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2025/4/2	MAKE	MOROOKA	MODEL	MST-1500VDR
SERIAL	035513		STAMP	035513	
HR METER	1392 / 1368	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700R	TIRE

ENGINE : MODEL QSB6.7		S/N 26743669	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	<input checked="" type="radio"/> YES	NO	
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS	<input type="radio"/> DD	No. OF GEARS 2 GEARS
Transmission	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
Swing	<input checked="" type="radio"/> FAIR	Attn	
Articulate	<input type="radio"/> FAIR	Attn	
FOOT BRAKE	<input type="radio"/> FAIR	Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	<input checked="" type="radio"/> CLEAN	<input type="radio"/> FAIR	<input type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C	<input type="radio"/> H only · <input type="radio"/> C only · None

MAIN FRAME	
MAIN FLAME	<input checked="" type="radio"/> FAIR · Attn
VESSEL	
VESSEL	<input checked="" type="radio"/> FAIR · Attn
REAR GATE TYPE	<input type="radio"/> NORMAL · <input type="radio"/> L-GATE (FLAT)
REAR GATE	<input checked="" type="radio"/> FAIR · Attn
UNDERCARRIAGE: See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	<input type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR
COMMENT	
<div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。