INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2025/3/11	MAKE	VOLVO	MODEL	A20
SERIAL	A20V2368		STAMP	A20V2368	
HR METER	10378 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE		TIRE F: 18.00-25 R: 20.5-25

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	No. OF GEARS 4 GEARS
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
Swing	FAIR・Attn	
Articulate	FAIR・Attn	シリンダーロッド傷あり CYLINDERS: SCRATCHED
FOOT BRAKE	FAIR・Attn	
PARKING BRAKE	FAIR・Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	破れあり TORN
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	

MAIN FRAME		
MAIN FLAME	FAIR・Attn	
VESSEL		
VESSEL	FAIR・Attn	腐食、穴あり CORRODED & HUGE HOLES
REAR GATE TYPE	NORMAL・L-GATE (FLAT)	
REAR GATE	FAIR・Attn	
UNDERCARRIAGE:	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR・WORN・UNEVEN WEAR	

COMMENT

プロペラシャフト亀裂あり PROPELLER SHAFT: CRACKED

CABドアジョイント部破損あり SOME DOOR HINGE: BROKEN

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。