INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DATE		2025/4/7		MAKE		HITACHI	M	MODEL		EG70R		
SERIAL	81SP010131				STAMP		NOT FOUND					
HR METER	6478 HR Odometer					km	YEAR			YR		
CAB/CNP	ROPS CA	B CAB R	OPS CN	IP / CNP /	/ NONE	SHOE	700	R	TIRE			
ENGINE: MODEL 6BG1 S/N						MAIN FRAME						
Oil leakage	FAIR · Attn					MAIN FLAME FAIR ・ (Attn) リペイントあり REPAINTED						
Blow-By	FAIR · Attn	A LITTLE · MIC	DLE •	SEVERE		VESSEL						
Sound	FAIR · Attn					VESSEL FAIR - Attn						
Oil	FAIR · Attn					REAR GATE TYPE NORMAL • L-GATE (FLAT)						
Exhaust Color	FAIR · Attn					REAR GATE FAIR · Attn 欠品 MISSING						
US EPA	YES · NO					UNDERCARRIAGE: See Photos. 写真参照						
OPERATION PUMP					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							
Sound	FAIR · Attn					TIRE WEAR FAIR • WORN • UNEVEN WEAR						
Oil leakage	FAIR · Attn					COMMENT	-					
Power	Power FAIR) · Attn					リペイントあり REPAINTED						
COOLING SYSTEM					CABステップ欠 SIDE STEP: MISSING							
Radiator	FAIR · Attn					左右シュー	·劣化、左	数ヶ所割	割れあり			
Oil Cooler	FAIR · Attn					RUBBER TRA	CKS: DETE	RIORATE	D, LEFT RU	BBER TRACK: C	RACKED	
TRANSMISSION & TRAVEL						*1 前進時左へ流れる TOTTERING TO LEFT DURING TRAVELING FORWARD						
T/M TYPE	PS) · DD		No. C	F GEARS 2	GEARS							
Transmission	FAIR · Attn		·	,								
Travel	FAIR · Attn	*1										
Swing	FAIR · Attn											
Articulate	FAIR · Attn											
FOOT BRAKE	FAIR · Attn											
PARKING BRAKE	FAIR · Attn											
INTERIOR See Photos. 写真参照												
INTERIOR COND.	CLEAN	· FAIR) D	IRTY								
Operator's Seat	FAIR · Attn											
Glasses	FAIR · Attn											
AirCon	A/C).	H/C · H or	nly •	C only •	None	RUST of BODY	(5: NONE, 4: A	LITTLE, 3: I	MIDDLE, 2: MU	CH, 1: CORRODED)	1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。