

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/3/21	MAKE	SUMITOMO	MODEL	SC1000-2
SERIAL No.	PLATE :	SC100-1026	STAMP	SC100-1026	
HR METER	3986	HR	SHOE	960FLAT	YEAR YR

ENGINE : MODEL		S/N	231089
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	
BOOM			
MAIN BOOM	TOP, BOTTOM, 9m × 4, 6m × 2, 3m × 2, 1m × 1		
BOOM TOTAL	74m		
TOP SHEAVE	YES	NO	
JIB			
TOWER	50m + 44m		
TOP, BOTTOM, 9m × 1, 6m × 2, 3m × 2			

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
WEIGHT			
4			
HOOK			
100t, 50t, 35t, BALL			
LIFTER			
YES · NO			
COMMENT			
9mブームに9mペンダント2本あり 2 OF 9m PENDANTS FOR 9m BOOM			
起伏ドラムモーター油漏れあり LUFFING DRUM MOTOR: OIL LEAKING			
*1 上部油漏れあり UPPER PART OF ENGINE: OIL LEAKING			
@NARITA YARD			
BOOM: TOP, BOTTOM, 9m × 1, 1m × 1			
HOOK: 50t, BALL			
@SAKURA YARD			
BOOM: 9m × 3, 6m × 2, 3m × 2, HOOK: 100t, 35t			
TOWER: TOP, BOTTOM, 9m × 1, 6m × 2, 3m × 2,			
SWING, CAP, CATCHER, GUIDE ROLLER			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。