INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DATE		2025/3/26			MAKE		IHI	M		DDEL	IC50		
SERIAL	CE003292				-	-	STAMP			-	CE003292		
HR METER	2770 HR			R Od	lometer		ŀ	km YEAR				YR	
CAB/CNP	ROPS CA) C	AB / RO	PS CI	NP / CNP	/ NONE	SHOE		600	R	TIRE		
ENGINE: MODEL S/N							MAIN FRAME						
Oil leakage	FAIR · Attn						MAIN FLAME FAIR - Attn						
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE						VESSEL						
Sound	FAIR · Attn						VESSE	L I	FAIR	Attn			
Oil	FAIR · Attn						REAR GATE	TYP€	$\langle z \rangle$	ORMAL		-GATE (FLAT)	
Exhaust Color	FAIR · Attn						REAR GA	ATE	FAIR	• (Attn	*1		
US EPA	YES · NO						UNDERCARRIAGE: See Photos. 写真参照						
OPERATION PUMP							RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						
Sound	FAIR · Attn						TIRE WE	AR	FA	AIR • W	ORN • UI	NEVEN WEAR	
Oil leakage	FAIR · Attn						COMMENT	-					
Power	FAIR · Attn						*1 自然に	閉まら	ない	UNAE	BLE TO C	CLOSE BY ITS	ELF
COOLING	SYSTEM												
Radiator	FAIR · Attn												
Oil Cooler	FAIR · Attn												
TRANSMISSION & TRAVEL													
T/M TYPE	PS) · DD			No.	OF GEARS 2	GEARS							
Transmission	FAIR · Attn			·	·								
Travel	FAIR · Attn												
Swing	FAIR · Attn												
Articulate	FAIR · Attn												
FOOT BRAKE	FAIR · Attn												
PARKING BRAKE	FAIR · Attn												
INTERIOR See Photos. 写真参照													
INTERIOR COND.	CLEAN	\cdot	FAIR •		DIRTY								
Operator's Seat	FAIR · Attn												
Glasses	FAIR · Attn												
AirCon	A/C ·	H/C	• (H on	<u>)</u>	C only •	None	RUST of BODY	(5: NONE	, 4: A L	LITTLE, 3: N	1IDDLE, 2: MU	CH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。