INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DAT		2025/3/18			MAKE		IHI		MC	DEL	IC50		
SERIAL	CE003338						STAMP				CE003338		
HR METER	2415 HR			IR Od	ometer		km YEAR					YR	
CAB/CNP	ROPS CA	AB / C	AB /	ROPS CN	NP / CNP /	/ NONE	SHOE		590I	₹	TIRE	_	
ENGINE: MODEL S/N							MAIN FRAME						
Oil leakage	FAIR · Attn						MAIN FLAME FAIR - Attn						
Blow-By	FAIR · Attn	A LITT	LE · MI	DDLE •	SEVERE		VESSEL						
Sound	FAIR · Attn						VESSE	EL	FAIR	 Attn 			
Oil	FAIR · Attn						REAR GATE	TYPE	\sqrt{N}	ORMAL		GATE (FLAT)	
Exhaust Color	FAIR · Attn						REAR GA	ATE	FAIR	 Attn 			
US EPA	YES · NO						UNDERCARRIAGE: See Photos. 写真参照						
OPERATION PUMP							RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4						
Sound	FAIR · Attn						TIRE WE	AR	FΑ	IR • W	ORN • UI	NEVEN WEAR	
Oil leakage	FAIR · Attn						COMMENT	-					
Power	FAIR · Attn												
COOLING	SYSTEM												
Radiator	FAIR · Attn												
Oil Cooler	FAIR · Attn												
TRANSMISSION & TRAVEL													
T/M TYPE	PS) · DD			No. 0	OF GEARS 2	GEARS							
Transmission	FAIR · Attn			·	·								
Travel	FAIR · Attn												
Swing	FAIR · Attn												
Articulate	FAIR · Attn												
FOOT BRAKE	FAIR · Attn												
PARKING BRAKE	FAIR · Attn												
INTERIOR See Photos. 写真参照													
INTERIOR COND.	CLEAN	>	FAIR	• D	IRTY								
Operator's Seat	FAIR · Attn												
Glasses	FAIR · Attn												
AirCon	A/C ·	H/C	• (H d	only •	C only •	None	RUST of BODY	(5: NONE	, 4: A L	ITTLE, 3: M	IIDDLE, 2: MU	CH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。