INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/2	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	27678			STAMP	KMTPC189A01027678
HR METER	6109 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL 4D95LE-5 S/N 526389		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
MAIN PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Swing	FAIR・Attn	
Travel	FAIR・Attn	*1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	破れ小 WORN
Glasses	FAIR・Attn	*2
AirCon	A/C・H/C・H only・C only・None	
BOOM / ARM / BKT		
Boom	FAIR・Attn	
Boom Cylinder	FAIR・Attn	
Arm	FAIR・Attn	
Arm Cylinder	FAIR・Attn	
BKT	FAIR・Attn	
BKT Cylinder	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG・WRIST	
Multi	MULTI・2・NO	
ARM-CRANE	YES・NO	
BLADE	YES・NO	
OFFSET	YES・NO	
OFFSET Cylinder	FAIR・Attn	
Piping	YES・NO	Breaker only・Multi 3 *3
COMMENT		
A/Cエラー表示あり A/C ERROR DISPLAY		
ドア欠 DOOR: MISSING		
右ボディコントロールバルブハッチ開かない、キャッチ不良		
RIGHT CONTROL VALVE COVER: UNABLE TO OPEN (LATCH: MALFUNCTION)		
*1 左レバーニュートラルに戻らない		
*1 LEFT TRAVEL LEVER: UNABLE TO RETURN		
*2 右ガラス割れ、欠品あり RIGHT SIDE GLASS: BROKEN		
*3 操作レバーS/W、ペダルがない NO SWITCH, NO PEDAL		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。