## INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION	ON DATE	2025/3/24	MAK	Ξ	KOMATSU		MODEL		HM300-3	
SERIAL	3695				STAMP	KMTHM011LFD003695				
HR METER	7331 HR Odometer		2	28730	km	YEAR			YR	
CAB/CNP	ROPS CA	AB / CAB / ROP	S CNP / CN	P / NONE	SHOE		·	TIRE	750/65F	25
ENGINE :	MODEL S/N				MAIN FRAME					
Oil leakage	FAIR · Attn			MAIN FLAME (FAIR) - Attn						
Blow-By	FAIR · Attn	A LITTLE · MIDDL	.E • SEVEF	RE	VESSEL					
Sound	FAIR · Attn				VESSE	EL FA	IR) • Attn			
Oil	FAIR · Attn				REAR GATE	TYPE	NORMA	L •€	GATE (FLAT)	
Exhaust Color	FAIR · Attn				REAR G	ATE FA	IR) • Attn			
US EPA	YES · NO				UNDERCARRIAGE: See Photos. 写真参照					
OPERATION PUMP					RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4					
Sound	FAIR · Attn				TIRE WEAR FAIR · WORN · UNEVEN WEAR					
Oil leakage	FAIR · Attn				COMMENT	Γ				
Power	FAIR · Attn				常に出てし	るわけ	ではない。	が30秒おる	きくらいに	
COOLING SYSTEM					L03アキュムレータ油圧低下警告が出る					
Radiator	FAIR · Attn				"L03" ERROR	DISPLAY F	OR LOW HYD	RAULIC ACC	SUMULATOR PRES	SURE:
Oil Cooler	FAIR · Attn							O	N/OFF PER 30 SE	CONDS
TRANSMIS										
T/M TYPE	PS) · DD		No. OF GEARS	5 GEARS						
Transmission	FAIR · Attn		,							
Travel	FAIR · Attn									
Swing	FAIR · Attn									
Articulate	FAIR · Attn									
FOOT BRAKE	FAIR · Attn									
PARKING BRAKE	FAIR · Attn									
INTERIOR See Photos. 写真参照										
INTERIOR COND.	CLEAN	· FAIR ·	DIRTY							
Operator's Seat	FAIR · Attn									
Glasses	FAIR · Attn									
AirCon	A/C).	H/C • H only	• C only	• None	RUST of BODY	(5: NONE, 4:	A LITTLE, 3: I	MIDDLE, 2: MU	CH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。