

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2025/3/14	MAKE	KOBELCO	MODEL	SK135SRD-5
SERIAL	YY08041282		STAMP	YY08041282	
HR METER	2373	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

**ENGINE : MODEL** 4JJ1 **S/N** 288961

Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	<input checked="" type="radio"/> YES · NO	

**MAIN PUMP**

Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	

**COOLING SYSTEM**

Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	

**OPERATING SYSTEM**

Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	

**INTERIOR See Photos. 写真参照**

INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

**BOOM / ARM / BKT**

Boom	<input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn	
Arm	<input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn	
BKT	<input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn	

**UNDERCARRIAGE : See Photos. 写真参照**

**RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)** 4

**COMMENT**

.....  
 .....  
 .....  
 .....

**BKT**  STD / SLOPE / NARROW / SKELETON / OTHER ( )

**Lever** LONG ·  WRIST

**Multi**  MULTI · 2 · NO

**ARM-CRANE**  YES · NO

**BLADE**  YES · NO

**OFFSET** YES ·  NO

**OFFSET Cylinder** FAIR · Attn

**Piping**  YES · NO Breaker only  Multi 5

**COMMENT**

.....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....  
 .....

**RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)** 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。