

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/13	MAKE	KOMATSU	MODEL	PC138US-10
SERIAL	43412			STAMP	UNREADABLE
HR METER	3284	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ガタあり SWING: LOOSE
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	*1
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	*2
Arm	FAIR • Attn	ガタあり LOOSE
Arm Cylinder	FAIR • Attn	*3
BKT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	腐食あり CORRODED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO シリンダー左右サビあり CYLINDERS: RUSTY
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi *4
COMMENT	
E/Gフードラッチ動かない(サビあり)、E/Gフード開閉不可	
ENGINE HOOD LATCH: STUCK (RUSTY), ENGINE HOOD: UNABLE TO OPEN	
配管類サビ多数あり MANY PIPES: RUSTY	
L03表示あり "L03" ERROR DISPLAY	
コンデンサーフィン破損あり MANY A/C CONDENSER FINS: BROKEN	
*1 天井ハッチガラス外れあり	
*1 EVACUATION HATCH GLASS AT CEILING: COME OFF	
*2 左右メッキ剥がれあり CYLINDERS: COATING PEELED	
*3 メッキ剥がれ、腐食あり COATING: PEELED, CORRODED	
*4 ペダル: サビで固着あり、動作不可	
*4 PEDAL: STUCK (RUSTY), UNABLE TO OPERATE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。