## INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTIO	ON DATE	DATE 2025/3/31		N	IOROOKA		MODEL	М	MST-200VDR	
SERIAL	20R138				STAMP		20R138			
HR METER	5	535 HR	Odometer	ometer –		k	m YEAR			YR
CAB/CNP	ROPS CA	AB / CAB / ROP	S CNP CNP	NONE	SHOE		300R	TIRE	_	
ENGINE :	MAIN FRAME									
Oil leakage	FAIR · Attn				MAIN FL/	AME	FAIR • Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDI	_E • SEVERE	<u> </u>	VESSEL					
Sound	FAIR · Attn				VESSE	EL	FAIR • Attn			
Oil	FAIR · Attn				REAR GATE	TYPE	NORMA	r-	GATE (FLAT)	
Exhaust Color	FAIR · Attn				REAR GA	ATE	FAIR • Attn			
US EPA	YES)· NO				UNDERCARRIAGE: See Photos. 写真参照					
OPERATION PUMP					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4					
Sound	FAIR · Attn				TIRE WE	AR	FAIR • W	ORN · UN	NEVEN WEAR	
Oil leakage	FAIR · Attn				COMMENT	-				
Power	FAIR · Attn				クルクルダ	ンプ	ROTATABL	LE CARRI	ER DUMPER	
COOLING SYSTEM										
Radiator	FAIR · Attn									
Oil Cooler	FAIR · Attn									
TRANSMIS										
T/M TYPE	PS) · DD		No. OF GEARS	2 GEARS						
Transmission	FAIR · Attn									
Travel	FAIR · Attn									
Swing	FAIR · Attn									
Articulate	FAIR · Attn									
FOOT BRAKE	FAIR · Attn									
PARKING BRAKE	FAIR · Attn									
INTERIOR										
INTERIOR COND.	CLEAN	· FAIR ·	DIRTY							
Operator's Seat	FAIR · Attn									
Glasses	FAIR · Attn									
AirCon	A/C •	H/C • H only	• C only	None	RUST of BODY	(5: NONE	, 4: A LITTLE, 3: 1	MIDDLE, 2: MU	CH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。