INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/3/21	MAKE	KOMATSU	MODEL	WA40-3
SERIAL	11326		STAMP	W030-11326	
HR METER	4375 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	15.5/60-18	

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
FOOT BRAKE	FAIR・Attn	
PARKING BRAKE	FAIR・Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	
Glasses	FAIR・Attn	*1
AirCon	A/C・H/C・H only・C only・None	
FRONT & CYLINDERS		
Arm	FAIR・Attn	*2
Bell crank	FAIR・Attn	
Bucket	FAIR・Attn	シリンダー油漏れ小 CYLINDER: OIL LEAKING
Articulate	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR	FAIR・WORN・UNEVEN WEAR		
COMMENT			
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	YES・NO		
ATTACHMENTS			
STD BKT	YES・OTHER		
BLADE	YES・NO	Piping for Tilt	YES・NO
COMMENT			
ヒーター動作しない HEATER: NOT WORKING			
*1 リアゲートラッチ掛からない REAR GATE LATCH: NOT WORKING			
*2 左右シリンダー油漏れあり CYLINDERS: OIL LEAKING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。