

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/3/18	MAKE	MITSUBISHI	MODEL	WS300		
SERIAL	2W000364			STAMP	2W000364		
HR METER	1703	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	15.5/60-18		

ENGINE : MODEL		S/N	1858
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	PS	DD	
Transmission	FAIR	Attn	
Travel	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり HUGE CUTS
Glasses	FAIR	Attn	*1
AirCon	A/C	H/C	H only · C only · None
FRONT & CYLINDERS			
Arm	FAIR	Attn	*2
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	*3
Articulate	FAIR	Attn	ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
作動油タンク穴あり HYDRAULIC OIL TANK: HOLE	
作動油白濁あり HYDRAULIC OIL: CLOUDY	
右CABドアラッチ破損あり、開かない	
RIGHT DOOR LATCH: BROKEN, RIGHT DOOR: UNABLE TO OPEN	
CAB後付け RETROFITTED CAB	
RPMメーター不良 TACHOMETER: MALFUNCTION	
配管ホースひび割れあり SOME HOSES: CRACKED	
ヒーター: ファン回らない HEATER FAN: UNABLE TO WORK	
*1 右ドアガラス割れあり RIGHT DOOR GLASS: CRACKED	
*2 ロングアーム、左シリンダーサビあり LONG ARM, LEFT CYLINDER: RUSTY	
*3 シリンダーサビ、傷あり CYLINDER: RUSTY, SCRATCHED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。