

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/3/21	MAKE	HITACHI SUMITOMO	MODEL	SCX550-C3
SERIAL No.	PLATE :	CX055-6722	STAMP	CX055-6722	
HR METER	7133	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 2, 6m × 2, 3m × 1	
BOOM TOTAL	43m	
TOP SHEAVE	☒ YES · NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	破れあり TORN
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
COMMENT		
WEIGHT	3	
HOOK	55t, 30t, 15t, BALL	
LIFTER	YES · ☒ NO	
COMMENT		
@NARITA YARD		
BOOM: TOP, BOTTOM, 6m × 1		
@SAKURA YARD		
BOOM: 9m × 2, 6m × 1, 3m × 1		
HOOK: 55t, 15t, BALL		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。