

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2025/3/28	MAKE	KOBELCO	MODEL	7045
SERIAL No.	PLATE : GM-00340	STAMP	00340		
HR METER	4879	HR	SHOE	760FLAT	YEAR YR

<b>ENGINE : MODEL S/N</b>	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn *1
<b>OPERATING SYSTEM</b>	
Computer	<input checked="" type="radio"/> OK · NG *2
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
<b>BOOM</b>	
MAIN BOOM	TOP, BOTTOM, 9m × 1, 6m × 3, 3m × 1
BOOM TOTAL	39m
TOP SHEAVE	<input checked="" type="radio"/> YES · NO
JIB	
TOWER	

<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
WEIGHT 3	
HOOK 45t, 35t, BALL	
LIFTER YES · <input checked="" type="radio"/> NO	
<b>COMMENT</b>	
*1 外側サビ大 OUTSIDE OF OIL COOLER: MUCH RUSTY	
*2 未確認、画面映り悪い NOT CHECKED, MONITOR: BLURRED	
@NARITA YARD	
BOOM: TOP, BOTTOM, 6m × 1	
45t HOOK	
@SAKURA YARD	
BOOM: 9m × 1, 6m × 2, 3m × 1	
HOOK: 35t, BALL	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。