INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/17	MAKE	HITACHI	MODEL	ZX200LC-3
SERIAL	HCM1U100T00221033			STAMP	HCM1U100T00221033
HR METER	9554 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
MAIN PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Swing	FAIR・Attn	
Travel	FAIR・Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	破れあり TORN
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
BOOM / ARM / BKT		
Boom	FAIR・Attn	
Boom Cylinder	FAIR・Attn	
Arm	FAIR・Attn	ガタあり LOOSE
Arm Cylinder	FAIR・Attn	
BKT	FAIR・Attn	穴大 HUGE HOLES
BKT Cylinder	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
両側ピンブッシュ割れ多数あり MANY PIN BUSHES: BROKEN		
両側スプロケット摩耗あり SPROCKETS: WORN		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG・WRIST	
Multi	MULTI・2・NO	
ARM-CRANE	YES・NO	
BLADE	YES・NO	
OFFSET	YES・NO	
OFFSET Cylinder	FAIR・Attn	
Piping	YES・NO	Breaker only・Multi
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。