

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/18	MAKE	CAT	MODEL	E120B
SERIAL	7NF05030		STAMP	7NF05030	
HR METER	7537	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり TORN
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	両側にじみあり CYLINDERS: OIL OOZING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	にじみあり OIL OOZING
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT 左側トラックローラー不良 SOME LEFT TRACK ROLLERS: MALFUNCTION	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER ())
Lever	LONG ▪ (WRIST)
Multi	MULTI ▪ 2 ▪ (NO)
ARM-CRANE	YES ▪ (NO)
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	YES ▪ (NO) Breaker only ▪ Multi
COMMENT 左サイドカバーラッチ不良 LEFT SIDE COVER LATCH: MALFUNCTION 左側走行レバー戻り悪い LEFT TRAVEL LEVER: HARD TO RETURN メインポンプ付近エアー抜け音あり(シューシューという音) AROUND MAIN PUMP: SOUNDS LIKE AIR LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。