

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/4	MAKE	KUBOTA	MODEL	U-10-3
SERIAL	20321		STAMP	20321	
HR METER	1820	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		SHOE	180R	

ENGINE : MODEL		S/N	BW2601
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		
MAIN PUMP			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
OPERATING SYSTEM			
Swing	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY		
Operator's Seat	FAIR · <u>Attn</u> 破れあり CUTS		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
BOOM / ARM / BKT			
Boom	<u>FAIR</u> · Attn		
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn		
Arm Cylinder	<u>FAIR</u> · Attn		
BKT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	MULTI · <u>2</u> · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。