

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/4/23	MAKE	KUBOTA	MODEL	RA500
SERIAL	NO PLATE			STAMP	RA500-10617
HR METER	3539	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP			TIRE SIZE	15.5/70-18 8PR

ENGINE : MODEL S/N Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA YES · ☒ NO OPERATION PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE ☒ PS · DD Transmission ☒ FAIR · Attn Travel ☒ FAIR · Attn FOOT BRAKE ☒ FAIR · Attn PARKING BRAKE ☒ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · ☒ FAIR · DIRTY Operator's Seat FAIR · ☒ Attn 破れあり CUTS Glasses FAIR · Attn AirCon A/C · H/C · H only · C only · ☒ None FRONT & CYLINDERS Arm ☒ FAIR · Attn Bell crank ☒ FAIR · Attn Bucket ☒ FAIR · Attn Articulate FAIR · ☒ Attn ガタあり LOOSE	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2 TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR COMMENT STEERING TYPE ☒ WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING RIDE CONTROL YES · ☒ NO ATTACHMENTS STD BKT ☒ YES · OTHER BLADE YES · ☒ NO Piping for Tilt YES · ☒ NO COMMENT 回転計、水温計、燃料計故障あり TACHOMETER, WATER TEMPERATURE GAUGE, & FUEL GAUGE: MALFUNCTION RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2
---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。