

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/8	MAKE	YANMAR	MODEL	VIO70-3A
SERIAL	36209B		STAMP	36209B	
HR METER	3722	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N	I7947
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn	油漏れ小 OIL LEAKING	
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn		
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
BKT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	STD · SLOPE · NARROW / SKELETON / OTHER()		
Lever	LONG · WRIST		
Multi	MULTI · 2 · NO		
ARM-CRANE	YES · NO		
BLADE	YES · NO		
OFFSET	YES · NO		
OFFSET Cylinder	FAIR · Attn		
Piping	YES · NO	Breaker only · Multi	
COMMENT			
A/C効かない A/C: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。