

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/1	MAKE	KUBOTA	MODEL	RX-505
SERIAL	72439		STAMP	72439	
HR METER	3759	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		S/N	7DY9027
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
MAIN PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
OPERATING SYSTEM			
Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • ☒ FAIR •	DIRTY	
Operator's Seat	☒ FAIR	Attn	破れあり CUTS
Glasses	☒ FAIR	Attn	
AirCon	A/C • H/C • H only • C only • ☒ None		
BOOM / ARM / BKT			
Boom	☒ FAIR	Attn	
Boom Cylinder	☒ FAIR	Attn	
Arm	☒ FAIR	Attn	
Arm Cylinder	☒ FAIR	Attn	
BKT	☒ FAIR	Attn	
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	☒ YES • NO
BLADE	☒ YES • NO
OFFSET	☒ YES • NO
OFFSET Cylinder	☒ FAIR • Attn
Piping	YES • ☒ NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。