

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/1	MAKE	KOMATSU	MODEL	PC78UU-8
SERIAL	18225	STAMP	KMTPC213P01018225		
HR METER	5745	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR • Attn	
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn	
Oil	☒ FAIR • Attn	
Exhaust Color	☒ FAIR • Attn	
US EPA	☒ YES • NO	
MAIN PUMP		
Sound	☒ FAIR • Attn	
Oil leakage	☒ FAIR • Attn	
Power	☒ FAIR • Attn	
COOLING SYSTEM		
Radiator	☒ FAIR • Attn	
Oil Cooler	☒ FAIR • Attn	
OPERATING SYSTEM		
Swing	☒ FAIR • Attn	
Travel	☒ FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY	
Operator's Seat	☒ FAIR • Attn	
Glasses	☒ FAIR • Attn	
AirCon	☒ A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	☒ FAIR • Attn	
Boom Cylinder	☒ FAIR • Attn	
Arm	☒ FAIR • Attn	
Arm Cylinder	☒ FAIR • Attn	
BKT	☒ FAIR • Attn	
BKT Cylinder	☒ FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	☒ YES • NO
BLADE	☒ YES • NO
OFFSET	☒ YES • NO
OFFSET Cylinder	☒ FAIR • Attn
Piping	YES • ☒ NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。