

INSPECTION SHEET 検品書  
ROLLER ローラー

INSPECTION DATE	2025/3/26	MAKE	SAKAI	MODEL	T2
SERIAL	32558		STAMP	TT1-32558	
HR METER	4464	HR	Odometer	13281	km
				YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			TIRE SIZE	14/70-20

<b>ENGINE : MODEL</b>	<b>S/N</b>	<b>UNDERCARRIAGE :</b>	See Photos. 写真参照
Oil leakage	<u>FAIR</u> · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	TIRE WEAR
Sound	<u>FAIR</u> · Attn		<u>FAIR</u> · WORN · UNEVEN WEAR
Oil	<u>FAIR</u> · Attn		<b>COMMENT</b> ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... ..... .....
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		
<b>OPERATION PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	PS · <u>DD</u>		
Transmission	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
FOOT BRAKE	<u>FAIR</u> · Attn		
PARKING BRAKE	<u>FAIR</u> · Attn		
<b>INTERIOR</b>		See Photos. 写真参照	
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY		
Operator's Seat	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
<b>OTHERS</b>			
Vibratory	<u>FAIR</u> · Attn		
Watering	<u>FAIR</u> · Attn		
Articulate	<u>FAIR</u> · Attn		
		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。