INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/19	MAKE	KOMATSU	MODEL	PC200-3
SERIAL	35865			STAMP	35865
HR METER	17277 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL S/N		
Oil leakage	FAIR ・Attn	にじみ、汚れあり OIL OOZING, OIL STAINS
Blow-By	FAIR・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	FAIR・ Attn	
Oil	FAIR・ Attn	
Exhaust Color	FAIR・ Attn	
US EPA	YES ・NO	
MAIN PUMP		
Sound	FAIR・ Attn	
Oil leakage	FAIR・ Attn	
Power	FAIR・ Attn	
COOLING SYSTEM		
Radiator	FAIR・ Attn	
Oil Cooler	FAIR・ Attn	
OPERATING SYSTEM		
Swing	FAIR・ Attn	
Travel	FAIR ・Attn	左足遅い LEFT TRACK: SLOW MOVING
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR・ Attn	
Glasses	FAIR ・Attn	*1
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	FAIR・ Attn	
Boom Cylinder	FAIR・ Attn	
Arm	FAIR・ Attn	
Arm Cylinder	FAIR・ Attn	
BKT	FAIR・ Attn	ガタあり LOOSE
BKT Cylinder	FAIR・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER / FORK GRAB)	
Lever	LONG ・ WRIST	
Multi	MULTI ・ 2 ・ NO	
ARM-CRANE	YES ・NO	
BLADE	YES ・NO	
OFFSET	YES ・NO	
OFFSET Cylinder	FAIR ・ Attn	
Piping	YES ・ NO	Breaker only ・ Multi
COMMENT		
CABドアラッチ不良 DOOR LATCH: MALFUNCTION		
*1 F下、右下欠		
*1 LOWER WINDSHIELD & LOWER RIGHT SIDE GLASS: MISSING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。