

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/4/7	MAKE	TOYOTA	MODEL	2SDT15		
SERIAL	NO PLATE			STAMP	2SDT15-10109		
HR METER	2695	HR	Odometer	32997	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5/65-20		

ENGINE : MODEL S/N Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA YES · ☒ NO OPERATION PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE ☒ PS · DD Transmission ☒ FAIR · Attn Travel ☒ FAIR · Attn FOOT BRAKE ☒ FAIR · Attn PARKING BRAKE ☒ FAIR · ☒ Attn 効かない MALFUNCTION INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · ☒ FAIR · DIRTY Operator's Seat ☒ FAIR · ☒ Attn 背もたれ調整不可 BACKREST: UNABLE TO LOCK Glasses ☒ FAIR · Attn AirCon A/C · H/C · H only · C only · ☒ None FRONT & CYLINDERS Arm ☒ FAIR · ☒ Attn *1 Bell crank ☒ FAIR · Attn Bucket ☒ FAIR · ☒ Attn 穴あり MUCH HOLES Articulate ☒ FAIR · ☒ Attn *2	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR COMMENT STEERING TYPE ☒ WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING RIDE CONTROL YES · ☒ NO ATTACHMENTS STD BKT ☒ YES · OTHER BLADE YES · ☒ NO Piping for Tilt YES · ☒ NO COMMENT Fカバー欠 FRONT COVER: MISSING 左ウインカー点灯あり、操作レバー欠 LEFT BLINKER LAMP AT THE OPERATION UNIT: ON (LEFT BLINKDER: NOT BLINKING), BLINKER LEVER: MISSING *1 左右シリンダー油漏れ、左シリンダーホースひび割れ、ガタあり *1 CYLINDERS: OIL LEAKING, LEFT HOSE: A LITTLE DAMAGED, LOOSE *2 左シリンダー油漏れ、ガタあり LEFT CYLINDER: OIL LEAKING, LOOSE RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。