

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/21	MAKE	KOMATSU	MODEL	PC138US-10NM
SERIAL	47698			STAMP	KMTPC245PHA047698
HR METER	5189	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ガタあり SWING: LOOSE
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	
Arm	FAIR • Attn	
Arm Cylinder	FAIR • Attn	
BKT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
ハーベスタ外れ HARVESTER: NOT ATTACHED (MAKE: KONRAD WOODY H50-W52273) ハーベスタホース破れあり SOME HARVESTER HOSES: CUTS ハーベスタ用モニターひび割れあり MONITOR SURFACE FOR HARVESTER: CRACKED ハーベスタホース周り油漏れあり SOME HOSES OF HARVESTER: OIL LEAKING ハーベスタの掴み動作や挟み動作を行うと警報が鳴る WARNING SOUNDS: ON WHEN GRABBING or CUTTING BY HARVESTER チェーンソー動作しない CHAINSAW: NOT WORKING ハーベスタ: 安全レバーを入れるかE/Gオフで自然降下する HARVESTER: HYDRAULIC DRIFT WHEN LOCKING BY THE SAFETY LEVER or TURNING OFF THE ENGINE	
BKT	STD / SLOPE / NARROW / SKELETON (OTHER))
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi 3
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。