

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/11/28	MAKE	YANMAR	MODEL	VIO10
SERIAL	?2318B SOME LETTER: UNREADABLE		STAMP	02318B	
HR METER	2709 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	200R	

ENGINE : MODEL		2TNE68	S/N	06203
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR		See Photos. 写真参照		
Operator's Seat	FAIR	Attn	破れあり HUGE CUTS	
Inside Cover	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	にじみあり OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
BKT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	STD	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · WRIST		
Multi	MULTI · 2 · NO		
ARM-CRANE	YES · NO		
BLADE	YES · NO		
OFFSET	YES · NO		
OFFSET Cylinder	FAIR · Attn		
Piping	YES · NO	Breaker only · Multi	
COMMENT			
左走行レバー取っ手欠 LEFT TRAVEL LEVER GRIP: MISSING			
プレートすごい薄い PLATE: VERY BLURRED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。